Installation Manual

2 Panels Mounting Bracket



Solar Bracket Solar System Manufacturer









L feet-3

















Step1. Connect 2pcs of L feet-1 and 3pcs of L feet-2 with Bolt -2(M8x25mm)







Step3. Connect the mounting bracket to 2pcs of L feet-3 and 2pcs of L feet-4 with Bolt -2(M8x25mm)



Step4. Install the U bracket-1 and U bracket-2 to the pole with bolt-1(M12x300mm) Pls note: the brackets do not include the pole. Pole diameter: $\Phi 110^{\sim} \Phi 220$ mm







Step5. Connect the L feets and U bracket with Bolt -2(M8x25mm)



Step6. Reinforce the rest 2pcs of L feet-3 to L feet-4 with tapping screw(ST6.3x25mm)







Step7. Finished.



